

## Silver-Line SL8 Drum

Problem: SL8 drum is not holding paper correctly

*Solution: Clean out cam slot for full operation!*



Dirty Endcap



Sawdust to Clean



Close Up



Screwdriver



Screwdriver pushes Cam Back



High Tech Tool



Straightener Clip



Poke slot, clean out dust



Cleaned Endcap



Full Movement of cam!

- 1) Look for sawdust built up in the endcap
- 2) Close the cams on a screwdriver or piece of 20 grit paper to move the cam away from the endcap, creating space.
- 3) Use a paperclip and compressed air to clean this area out between the cam & endcap
- 4) Remove the screwdriver or paper to check for complete motion
- 5) Repeat the process until the space is completely cleared.

**Note: This process should be done on a regular basis to ensure proper action of the drum.**